

GLENDAL, ARIZONA

LOC I-LUF 108.7	APCH CRS 033°	Rwy Idg TDZE 1074 Arprt Elev 1084	AL-321 [USAF]
LUKE AFB (KLUF)			ALSF-1

ATIS ★
134.925 269.9

APP CON
118.15 363.125

TOWER ★
119.1 379.9

GND CON
133.175 335.8

CLNC DEL
126.25 273.475

When ALS inop, increase RVR to 40 and vis to ¾ mile.
When ALS inop, increase vis 1½ miles.

MISSED APPROACH: Climbing to 4000, intercept LUF TACAN R-033 to 12 DME (JOKVI). Contact LUKE APP CON.

LENNI 22 12,000 GS 3.00° TCH 55	CASIB 16 7000 5000 Arc 16	OSELE R-285 5000 5000 Arc 16
--	--	---

VGSI and GS Angle not coincident.

4000
LUF R-033
JOKVI
12
TACAN
2600
2.2
1.3
4.1 NM
0.5 NM

ELEV 1084 TDZE 1074	1214 1216 1218 1220 1222 1224 1226 1228 1230 1232 1234 1236 1238 1240 1242 1244 1246 1248 1250 1252 1254 1256 1258 1260 1262 1264 1266 1268 1270 1272 1274 1276 1278 1280 1282 1284 1286 1288 1290 1292 1294 1296 1298 1300	033° 4.6 NM from FAF HRL all rwy's
--------------------------------------	--	---

CATEGORY	C	D
S-ILS 3R *	1274/24	200 (200-½)
S-LOC/ DME 3R **	1560/50	486 (500-1)
SIDESTEP 3L	1560-2½	483 (500-2½)
CIRCLING	NOT AUTHORIZED	